



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

July 22, 2013

Reviewed: 

Mine Name: Dog Valley Mineral Mine	Permit Number: S/015/0101
Operator Name: United Minerals LLC	Inspection Date: July 18, 2013
Inspector(s): Wayne Western	Time: 2:30 – 3:00
Other Participants: none	Mine Status: ACT
Weather Condition: warm and partly cloudy	Last Inspection: NA
Bond Renewal Date: May 26, 2015	Bond Amount: \$16,300.00
Surface Ownership: SITLA	Mineral Ownership: SITLA
Last Year of Production: 2012	Acreage: 3 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Note: there are two site associated with this permit.

Inspection Summary:

The two sites each have highwalls with near vertical faces.

The overburden material is stockpiled but the location of the topsoil is not clearly marked.

The sites are stable and there does not appear to be any erosion.

Inspection Date: July 18, 2013

Page 2 of 4

S/015/0101


Roads into the site are in good condition. There is a well not far from the sites.

Conclusions and Recommendations:

The Division should continue to monitor

Directions to Site:

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne Waters", written over a horizontal line.

WHW:

cc: (OPERATOR)

ggochnour@blm.gov

O:\M015-Emery\S0150101-DogValleyMineralMine\inspections\INS-07172013.doc



North pit highwall and pit floor



North pit highwall and spoil pile



South pit highwall



South pit with spoil pile and high wall